

adderburypc.co.uk>;keith.mitchell@adderburypc.co.uk<keith.mitchell@adderburypc.co.uk>;ian.bailey221@gmail.com
adderburypc@hotmail.com<adderburypc@hotmail.com>

amage to the sports pitches that have been constructed on Land North Of Milton Road, Adderbury under planning consen
sion.

l drainage system includes an infiltration basin that has a minimum capacity of 100.8 m³ and a minimum infiltration a
and implemented has a capacity of just 8.0 m³ and an infiltration area of just 12 m².

g permission was introduced by Cherwell District Council following consultation with Drainage Engineers at Oxfordshire
n Council, as the developer, had to commission qualified Drainage Engineers (Forge Engineering Design Solutions) to d
e that there was no increased risk of flooding to surrounding land and properties. Given the foregoing it is clear that t
t been met.

graphs of the outfall detail that has actually been constructed by DW Clark and two of the consented drawings detailing
no. 3 of the planning permission. It is clear from the attachments that the required infiltration basin simply has not be
does not exist. The problem is further exacerbated by DW Clark installing a piped connection (which is not part of the
ght to the low lying areas of Horn Hill Road which, as you may know, was the area that was flooded in 2016 following a
recognised association who represents them, what we can do to support them and ensure that the drainage associated
mission. Some of these members, who are also represented by Adderbury Parish council, live and own properties in l

gation to communicate with our membership (APC Parishioners) and inform them what Adderbury Parish Council are
t is under construction on Land North of Milton Road, Adderbury. The fact currently is that their properties are at an i

cales, when the corrected drainage scheme will be in place.